

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Victor M. Kern
12485 150th St
Wadena, MN 56482
10-20-2003

Block Layers Lock


Adjustable Range 15 1/2" to 19 1/4"



Victor M. Kern
12485 150th st
Wadena, MN 56482

10-20-2003


Block Layer Lock



Block Layer Lock


Victor M. Kern
12485 150th St
Wadena, MN 56482
10-20-2003

PAGE 2 OF 1 DRAWINGS.



Victor M. Kern
12485 150th st
Wadena, MN 56482
10-20-2003

Block Layer Lock



Victor M. Kern
12485 150th St
Wadena, MN 56482
10-20-2003


Block Layer Lock PAGE 4 OF 1 DRAWINGS,

Block Layer Lock

Top View Of Right & Left Sides

Adjustable Range From 1 $\frac{1}{2}$ " to 19 $\frac{1}{4}$ "

Inserted Bubble Level



Victor M.Kern
12485 150th St
Wadena, MN 56482
10-20-2003


Block Layer Lock

Handle Assembly

Top View




Right Side





Left Side



Side View



Right Side



Right Side

Left Side

